

ALTERNATE METHOD OF COMPLIANCE (AMOC)

AD	Description	FAA Approval	Aircraft	STC
AD 98-11-04 R1	AMOC for Pats Aux fuel Tanks - SSID	120S-03-644	737-200	SA1078NE
AD 98-11-04 R1	AMOC for Pats Aux fuel Tanks - SSID	120S-03-644	737-100 -200	SA725NE
AD 98-11-04 R1	AMOC for Pats Aux fuel Tanks - SSID	120S-03-644	737-200	SA83NE
AD 98-11-04 R1	AMOC for Pats Aux fuel Tanks - SSID	120S-03-644	737-200	ST1265EA
AD 98-11-03 R1	AMOC for Rogerson Aux fuel Tanks - SSID	120S-03-643	727-100	SA1979NM
AD 98-11-03 R1	AMOC for Rogerson Aux fuel Tanks - SSID	120S-03-643	727-100	SA3710WE
AD 98-11-03 R1	AMOC for Rogerson Aux fuel Tanks - SSID	120S-03-643	727-200	SA3674WE
AD 98-11-03 R1	AMOC for Rogerson Aux fuel Tanks - SSID	120S-03-643	727-100	SA2734WE
AD 98-11-03 R1	AMOC for Rogerson Aux fuel Tanks - SSID	120S-03-643	727-100	SA37483WE
AD 98-11-03 R1	AMOC for Rogerson Aux fuel Tanks - SSID	120S-03-643	727-100	ST01623AT
AD 98-11-03 R1	AMOC for Pats Aux fuel Tanks - SSID	120S-03-642	727-100	SA62NE
AD 98-11-03 R1	AMOC for Pats Aux fuel Tanks - SSID	120S-03-642	727-200	SA84NE
AD 98-11-03 R1	AMOC for Pats Aux fuel Tanks - SSID	120S-03-642	727-100 -200	SA387NE
AD 98-11-03 R1	AMOC for Pats Aux fuel Tanks - SSID	120S-03-642	727-100	SA392NE
AD 98-11-03 R1	AMOC for Pats Aux fuel Tanks - SSID	120S-03-642	727-200	SA450NE
AD 98-11-03 R1	AMOC for Pats Aux fuel Tanks - SSID	120S-03-642	727-200	SA496NE
AD 98-11-03 R1	AMOC for Pats Aux fuel Tanks - SSID	120S-03-642	727-100	SA530NE
AD 98-11-03 R1	AMOC for Pats Aux fuel Tanks - SSID	120S-03-642	727-100	ST00466NY
AD 98-11-04 R1	AMOC for Pats Aux fuel Tanks - SSID	120S-03-0645	737-200	SA1054NW
AD 98-11-03 R1	Repair to BS 740 bulkhead outer chord at STR S-26R (SSID inspection Item F-25A, para (g))	120S-03-552	727	
AD 98-11-03 R1	DTA assessment of 5 Antennas, the VIP Interior configuration, The Raisbeck Engine Hushkit, and Aux Fuel System	120S-02-501	727	ST004485E

ALTERNATE METHOD OF COMPLIANCE (AMOC)

AD	Description	FAA Approval	Aircraft	STC
AD 98-11-03 R1 AD 2002-07-09 para(g)	Winters Aux Fuel Tanks		727	SA1474SO
AD 94-12-09 AD 2004-07-22	Fuselage Skin Lap Repair	120S-03-173 (time limited) 120S-04-114 (extension) 120S-04-220	747-100	
AD 2002-24-05	Wing rear spar upper chord	120S-03-316 (AMOC Request)	727	
AD 91-24-11 R1	Repair to Left and Right BS870 terminal fittings	120S-03-0182	727	
AD 94-12-09	Repair of Skin Lap corrosion	120S-03-173 (time limited)	747-100	
AD 98-11-03 R1	Repair of Skin at the edge of the Main Cargo Door Doubler	120S-02-1100	727	SA1797SO SA1798SO
AD 94-17-01 AD 94-15-18		120S-02-1026 (time limited)	747	
AD 2002-10-10	BS 400 Bulkhead replacement - Crack	120S-02-1020	747-100	
AD 92-06-06	Request - Repair to Main Cargo Door Hinge Lug		Convair 440	
AD 2000-17-04 para. (a) AD 91-07-04 para. (a) AD 89-09-03 para. (a) AD 92-25-09 para. (c) (d)(e)) (f) (g)	Lap joint repair at Str 10 L between BS 360 and 540	120S-01-1268	737-200	
AD 2000-17-04 para. (a) AD 89-09-03 para. (a) AD 92-25-09 para. (c) (d)(e)) (f) (g)	Lap joint repair at Str 4 L between BS 727 and 908	120S-01-1270	737-200	
AD 2000-17-04 para. (a) AD 91-07-04 para. (a) AD 89-09-03 para. (a) AD 92-25-09 para. (c) (d)(e)) (f) (g) AD 97-22-07 para (f) (g)	Lap joint repair at Str 10R and 10L between BS 727 and 908	120S-01-1271	737-200	

ALTERNATE METHOD OF COMPLIANCE (AMOC)

AD	Description	FAA Approval	Aircraft	STC
AD 2000-17-04 para. (a) AD 91-07-04 para. (a) AD 89-09-03 para. (a) AD 92-25-09 para. (c) (d)(e) (f) (g)	Lap joint repair at Str 14R between BS 360 and 540	120S-01-1272	737-200	
AD 2000-17-04 para. (a) AD 91-07-04 para. (a) AD 89-09-03 para. (a) AD 92-25-09 para. (c) (d)(e) (f) (g)	Lap joint repair at Str 14L through 20L between BS 908 and 1016	120S-01-1273	737-200	
AD 2000-17-04 para. (a) AD 91-07-04 para. (a) AD 89-09-03 para. (a) AD 92-25-09 para. (c) (g) AD 97-22-07 para (f) (g) AD 89-22-04 (b)	Lap joint repair at Str 14R between BS 727 and 908	120S-01-1279	737-200	
AD 2000-17-04 para. (a) AD 89-09-03 para. (a) AD 92-25-09 para. (c) (d)(e) (f) (g)	Lap joint repair at Str 4L between BS 500 and 540	120S-01-1280	737-200	
AD 2000-17-04 para. (a) AD 91-07-04 para. (a) AD 89-09-03 para. (a) AD 92-25-09 para. (c) (d)(e) (f) (g)	Lap joint repair at Str 14R between BS 331 and 360	120S-01-1281	737-200	
AD 2000-17-04 para. (a) AD 89-09-03 para. (a) AD 92-25-09 para. (c) (d)(e) (f) (g)	Lap joint repair at Str 10L between BS 345 and 360	120S-01-1282	737-200	

ALTERNATE METHOD OF COMPLIANCE (AMOC)

AD	Description	FAA Approval	Aircraft	STC
AD 2000-17-04 para. (a) AD 89-09-03 para. (a) AD 92-25-09 para. (c) (d)(e) (f) (g)	Lap joint repair at Str 10L between BS 345 and 360	120S-01-1284	737-200	
98-11-03 R1		120S-01-290	727	SA2734WE
91-11-01 94-15-18 2002-10-10	Corrosion Repair of BS 520 Frame between S47R and S47L	120S-03-762	747-200	
98-11-03 R1		120S-01-1325	727	SA1664SO- Exec Interior SA2612SO- Ovrbd Service/Lav Drain SA496NE- Aux Fuel Tank ST00166AT- TCAS SIP DWG 7235-FM67- S01-PS Antenna SIP DWG 7275-SC176- S01- SATCOM AVCRaft DWG B16- 3166-E-100 - Unilink Antenna UG DWG B727-2312- 2412 -UHF Antenna
98-11-03 R1		120S-00-947	727	SA3810WE
98-11-04 R1	Skin Penetrations due to install of a TCAS II, an upper L-Band antenna, Lower L-Band Antenna relocations, a GPS , an Aux fuel tank, and misc repairs	120S-02-1174 120S-01-604	737	SA00981CH
97-05-08	Repair and inspection of Hole "G" forward support fitting of the #3 Engine	120S-00-998	727	

ALTERNATE METHOD OF COMPLIANCE (AMOC)

AD	Description	FAA Approval	Aircraft	STC
98-11-03 R1	PATs Aux Fuel Tank Install in Lower Cargo Compartments	ANM120S-00-122	727	SA62NE SA84NE SA387NE SA392NE SA450NE SA496NE SA530NE ST00466NY
2007-19-07	Skin Lap Joint inspections	120S-09-75	757-200PCF	ST01529SE
2000-05-29 2001-02-01	Weather Radar Installation at BS 178 Forward Pressure Bulkhead	120S-09-676	737-200-300	SA1441NM SA7005NM-D SA7040NM-D(A)
98-11-04 R1	AMOC for Pats Aux fuel Tanks - SSID	120S-09-337a 120S-09-337	737-200	SA1054NW
2008-09-13	AMOC for Rockwell Collins HF Comminucations System	120S-09-741	737-400	ST00309SE-D
2008-09-13 98-11-04R1		120S-10-19		SA5185NM SA7041NM-D ST00208SE-D ST00586SE-D